

November, 1964

TO: ALL ROOTES DEALERS
MODEL: SUNBEAM IMP
SUBJECT: HEATER INEFFICIENCY


Isolated cases of heater inefficiency have been reported and investigation has shown that Bulletin R-1 has not been fully followed, the fault being traced to either:-

- (1) Adjustment of water valve heater.
- (2) Heater hoses kinked or incorrect run.
- (3) Air in cooling system and necessity for bleeding.

In the event of a retail customer complaining of inefficient heater, the Bulletin R-1 should be followed to the letter.

In the event of dealers still not being fully satisfied with the heater performance, contact should be made with this office with a view to fitment of an alternative heater matrix.

ROOTES MOTORS INCORPORATED


Kenneth Langridge
General Service Manager

KL/jd