

SERVICE BULLETIN

ENGINE

No.

To:

ALL ROOTES DEALERS

SUBJECT: CYLINDER HEAD GASKET

MODEL:

ALL LIGHT CAR RANGE

Complaints of cylinder head gasket leak have resulted in double checking of torque leadings during production and changes in head gasket design. This change is effective on:-

It is important that in the event of a warranty being completed on any of the affected cars, the gasket must be returned to the Wholesale Service Office with the warranty claim. Until further notice, no warranty claim affecting cylinder head will be honored unless this procedure is adhered to.

ROOTES MOTORS INCORPORATED

Kenneth Langridge General Service Manager

KL/jd