

SERVICE BULLETIN

GENERAL ANDA OVERDRIVE

Na

E-15

SEPT. 1965

TO:

ALL ROOTES GROUP DEALERS

MODEL:

LIGHT CAR RANGE: ALL SYNCHRO GEARBOX

SUBJECT:

DIFFICULT ENGAGEMENT OF 3RD & 4TH GEARS (FLOOR CHANGE

MODELS)

Should it be found necessary to investigate a complaint of difficult engagement of 3rd and 4th gear on floor change models, due to the gear lever catching the reverse position detnet, it is recommended that the following work is carried out:-

- 1. Remove the gearbox tunnel rear cover, exposing the reverse plunger cover, etc.
- 2. Remove the reverse plunger cover, spring and plunger
- 3. Carefully chamfer the mouth of the plunger bore until clean selection of 3rd and top gear is obtained with the plunger and spring, etc., fitted.

Please advise your Parts Manager of this information.

ROOTES MOTORS INCORPORATED

Kenneth langridge

General Service Manager