

SERVICE BULLETIN

GEARBOX OVERDRIVE

No. E-6

To:

ALL ROOTES DEALERS

MODEL:

HILLMAN, SUNBEAM & ALPINE

SUBJECT: ENGINE/TRANSMISSION HARSHNESS

Should you be called upon to rectify a complaint of engine vibration and/or transmission harshness, etc., it is recommended that the following work is carried out prior to any further investigation:-

Remove the gearbox tunnel carpet and cover plate round the gear lever.

Check for any signs of a condition of foul between the gearbox top cover remote control and the floor tunnel.

Should such a condition exist, lightly lever the tunnel away from the cover, ensuring a clearance of approximately 1/2" (1.27 cm).

ROOTES MOTORS INCORPORATED

Kenneth Langridge

General Service Manager

KL/jd