


SUBJECT - CONNECTING ROD BOLT TORQUE

Workshop Manual 143, Page 20, contains reference to connecting rod bolt torque as being 40-45 ft. lbs.

This is an error, the correct reading being 19-24 ft. lbs.

Will addressees please bring this to the attention of Service personnel and alter the W.S.M. accordingly.

ROOTES MOTORS INCORPORATED


Kenneth Langridge
General Service Manager

KL/jd