

SERVICE BULLETIN

No.

ISSUE 5 - JANUARY, 1965

SUBJECT - BRAKE PIPE LAYOUT

All cars prior to Chassis Number B.9470558 must be checked to ensure that the brake line adjacent to the S.U. fuel pump closely follows that illustrated in the attached sketch.

In the event of the brake hydraulic line taking an alternative run, this should be immediately, rerouted so as to ensure no possible foul can occur between the fluid line and the propshaft coupling.

Some benefit may be gained by re-forming the anchor bracket retaining the flexible and Bundy tubing at right angles to floor panel.

The attached sketch shows the correct routing of the brake line.

ROOTES MOTORS INCORPORATED

Kenneth Langridge

General Service Manager

KL/jd Enc.

NOTE: SKETCH IS MISSING