

January 1963

TO: ALL ROOTES GROUP DEALERS

SUBJECT: FUEL GAUGE INOPERATIVE

MODEL: SUPER MINX MARK II

Under exceptional circumstances, it is possible that the rear wing mounted fuel tank in the Mark II Super Minx can be completely insulated from the frame of the vehicle. This will prevent operation of the fuel gauge tank unit.

This condition can arise if the fibre washers, Part No. 9078027, Item 25, Page UAl in the relevant Parts Catalogue, are positioned so as to insulate the petrol tap from the banjo bolt, tap to pump. Replacement of one of the fibre washers by an aluminium or copper washer will restore the circuit.

In Production, aluminium washers have been fitted from Chassis Nos:-

B-1302668 Left and Right Hand Drive.

ROOTES MOTORS INCORPORATED

K. Langridge
General Service Manager