

PARTS
ROOTES
SERVICE

SERVICE BULLETIN

AUTOMATIC
TRANSMISSION

No63/1

March 1963

TO: ALL ROOTES GROUP DEALERS

SUBJECT: AUTOMATIC TRANSMISSION MODEL "35"

MODEL: HILLMAN MINX SUPER.


To correct any misunderstandings on proper fluid changes of the type "35" Automatic, The owner should be directed to the Automatic Transmission Handbook page 11, "Fluid Changes".

The Super Minx owners Handbook lubrication chart on the rear cover under 6000 mile service, Transmission, deals with the Smiths Automatic Transmission and not the Borg-Warner type "35" Transmission

IMPORTANT:

The Borg-Warner type "35" Transmission requires
NO FLUID CHANGE

ROOTES MOTORS INCORPORATED


K. Langridge
General Service Manager