

PARTS
ROOTES
SERVICE

SERVICE BULLETIN

ELECTRICAL

No. 63/15

MAY 1963

TO: ALL ROOTES GROUP DEALERS

SUBJECT: SHORTING OF MAP LIGHT HOT LEAD

MODEL: SUNBEAM ALPINE SERIES III

It has come to our notice that isolated cases of shorting of the map light hot lead has occurred at the glovebox metal surround.

Will all dealers cooperate in checking this point on P.D.I or at 1000 mile free service. The glove box surround should be removed and a relief filed into the metal work at point of contact with the live lead of map light.

This modification has been carried out in production and a chassis number break off will be issued in the near future.

Please bring this to the attention of all service personnel concerned.

ROOTES MOTORS INCORPORATED

Kenneth Langridge
General Service Manager

