## SERVICE BULLETIN

TRANSMISSION CLUTCH

No. 63/4

February 1963

TO: ALL ROOTES GROUP DEALERS

SUBJECT: TYPE "D" OVERDRIVE HYDRAULIC KNOCK

MODEL: SUNBEAM SERIES, ALPINE & RAPIER

Further to Bulletin 202 Dated Sept. 26, 1960, a modification has been introduced in production to eliminate hydraulic knock. This consists of the inclusion of a bleed hole in the operating valve body and enlarging the diameter of the operating valve stem exhaust port.

Overdrive units with serial numbers 25/3082, 25/3083 and subsequent numbers have been modified as described above.

Units with these serial numbers must not be modified as suggested in Fulletin E.2.

Modified overdrive units are fitted in production from the following chassis numbers:-

Sunbeam Rapier IIIA - D.3054578 Sunbeam Alpine - B.9108239

Please bring the foregoing to the attention of all concerned.

POOTES MOTORS INCORPORATED

Kenneth Langridge General Service Lanager