

January 1963

TO: ALL ROOTES GROUP DEALERS

SUBJECT: PETROL FILLING

MODEL: HILLMAN SUPER MINX MARK I

It has been brought to our notice that isolated cases of petrol filling difficulties have been reported to Dealers.

In the event that such difficulties are brought to your attention, it is suggested that the outline on Page 2 be followed by re-routing the existing vent pipes and sealing up the old vent hole in the filler neck.

Kindly bring the above to the attention of all concerned.

ROOTES MOTORS INCORPORATED

K. Langridge
General Service Manager

L/H

R/H

