

June 21, 1961

TO ALL ROOTES GROUP DEALERS

HYDRAULIC BRAKE AND CLUTCH COMPONENTS

During the last few months, a marked increase in the number of hydraulic units being changed as defective under Guarantee Claim procedure has been noted.


A number of these units have therefore been examined and a high percentage are found to be perfectly satisfactory and should not have been changed.

Where a faulty hydraulic component is suspected, it is most important that a very careful check is made before a replacement is fitted. In this connection, we feel sure that the principles of operation of the hydrostatic clutch slave cylinder are often misunderstood, giving rise to a belief that a hydraulic build up has occurred in the clutch system. Please make certain that all are aware of the hydrostatic slave cylinder's working principles. There is no free movement in this self-adjusting hydraulic linkage and no pull off spring, clutch release commencing immediately the pedal is depressed.

Kindly bring the above to the attention of all concerned at your location.

ROOTES MOTORS INCORPORATED

FJMcG:SO


E. J. McGettrick
Manager
Wholesale Parts & Service Depts.