

May 1964

TO: ALL ROOTES GROUP DEALERS
 MODEL: HILLMAN V. SUPER MINXII. SUNBEAM ALPINE IV.
 SUBJECT: BORG WARNER 35 TRANSMISSION - LINKAGE ADJUSTMENT

An additional 6th transmission selector lever position has been introduced by Borg Warner on the Model 35 transmission.

We shall continue to use 5 selector positions i.e., L.D.N.R.P., the additional detent being beyond 'L'. This can be selected with the hand linkage disconnected and in our application will give a neutral condition.

The modified unit will be identified initially be a blue painted 'D' on the convertor housing.


SELECTOR LEVER LINKAGE ADJUSTMENT

The Workshop Manual instruction for linkage adjustment is being altered and you will receive the amendment sheets shortly. The adjustment of the floor mounted selector lever is also covered.

INTRODUCTION POINTS

	<u>Serial No.</u>	<u>Unit No.</u>
Hillman V	B. 0321310	EP 9609
Super Minx II	B. 1346075	EP 9609
Alpine IV	B. 9402804	3EP 1526

ROOTES MOTORS INCORPORATED


 Kenneth Langridge,
 General Service Manager