

SERVICE BULLETIN

MISCELLANEOUS DOOR LOCKS ALL MODELS

No 215

December 5, 1960

TO ALL ROOTES GROUP DEALERS

It has come to our notice that many door locks are being changed under Guarantee when meeting owner criticisms of stiff operation etc., and it would appear that no attempt has been made to lubricate the mechanism.

In all cases of this nature the polythene access button which will be found on the door shut face must be removed and the lock mechanism lubricated by graphite before any dismantling is carried out. It will be found normally that lubrication is all that is required.

Kindly bring this to the attention of all concerned.

ROOTES MOTORS INCORPORATED

FJMcG:SO

F. J. McGettrick

Manager

Wholesale Parts & Service Depts.