

November 10, 1961

TO ALL ROOTES GROUP DEALERS

SUNBEAM RAPIER - SERIES III & IIIA

Improved double lipped piston seals and new retainers have been introduced to overcome complaints of disc brake caliper piston sticking.

Tests show that by employing this new seal any tendency for foreign matter to reach the piston bore is considerably reduced.

The modified assembly is directly interchangeable with the earlier type and you are recommended to fit these if complaints of piston sticking or seizure are brought to your notice.

COMPONENT

PART NUMBER

Piston Seal and Retainer


5039706

Introduction Chassis No. B.3055735.

Kindly bring the foregoing to the attention of all concerned.

ROOTES MOTORS INCORPORATED

FJMcG:SO


F. J. McGettrick
Manager

Wholesale Parts & Service Depts.