

PAGE I OF I
NOVEMBER, 1965

TO: ALL ROOTES DEALERS

MODEL: ALL MODELS EXCEPT HUSKY III & COB III

SUBJECT: WATER TEMPERATURE GAUGE & FUEL GAUGE INACCURACY

Where called upon to investigate complaints of inaccurate operation of the water temperature gauge transmitter, Part Number 1205552, or the fuel gauge, it is recommended that the following action is taken before any replacement material is fitted:-


1. Ensure that the temperature gauge and/or fuel gauge wires are connected to the 'I' connector on the voltage stabiliser and NOT to the 'B' connector.
2. Ensure that the Voltage stabiliser is correctly mounted, i.e., with the letters B and E at the top and installed within 2° of the vertical in both planes.
3. Ensure that the voltage stabiliser is effectively earthed through its mounting lug.

NOTE

It is important to ensure that all remaining electrical connections in the water temperature and fuel gauge circuits are correct as per the wiring diagram in the relevant Workshop Manual.

Please ensure that your Parts Manager receives this advice.

ROOTES MOTORS INCORPORATED


Kenneth Langridge
General Service Manager