

PARTS
ROOTES
SERVICE

SERVICE BULLETIN

ELECTRICAL
SYSTEM

No.N-5


November, 1964

TO: ALL ROOTES DEALERS
MODEL: SUNBEAM IMP
SUBJECT: TRAFFICATOR PAWL UNITS

Where complaints of trafficator pawl unit failures are encountered, it is recommended that the latest improved pawl unit, Part Number 7080224, (Lucas 34901B) is fitted.

These pawl units will be supplied less the mounting bracket and are interchangeable with the existing units provided a striker bush is already fitted within the outer column as illustrated in Workshop Manual 141, Section 'j', Figure 7.

ROOTES MOTORS INCORPORATED


Kenneth Langridge
General Service Manager

KL/jd