

ENGINE

No. B-6

PAGE I OF I

JULY-1964

TO: ALL ROOTES GROUP DEALERS  
MODEL: SUNBEAM IMP  
SUBJECT: IGNITION SETTING

It would not appear to be generally appreciated by Dealers that it is extremely important to ensure that the ignition timing is accurately set on engines having such high compression ratios as on the Sunbeam Imp.

When investigating complaints of excessive fuel consumption, lack of performance, etc., the static ignition must be checked according to instructions in the Workshop Manual.

The correct static ignition setting is  $3^{\circ}$  (3 mm) before top dead centre.

ROOTES MOTORS INCORPORATED

*K Langridge*  
Kenneth Langridge  
General Service Manager

jd