

## SERVICE BULLETIN

COOLING SYSTEM

No. A-1

To:

ALL ROOTES GROUP DEALERS

MODEL: ALL MODELS

SUBJECT: FAN BELTS

On a number of cars, transient owners have been unable to obtain fan belts from our dealers due to lack of stock and consequently, been held up for a period while a fan belt has been obtained.

This has affected the Humber chiefly and for dealer information, the following fan belts can be fitted to our products in the event of non-stocking.

It must be pointed out that the retail cost of these belts are higher than the standard Rootes belt and as such, these belts should only be used in an emergency:-

MODEL	ATIAS	BOWES	FIRESTONE	GATES	GOODYEAR U.S. ROYAL
Hillman Sunbeam Super M <sub>i</sub> nx Husky	) ) 681 )	364 or 299	V29M	8206	404H V159
Humber	701	371	3-J-328	8264 8290	3021H 3066H V194

Humber power steering belt - U.S. Royal 4L270

ROOTES MOTORS INCORPORATED

Kenneth Langridge General Service Manager