

SERVICE BULLETIN

ENGINE

No. B-1

January, 1964

10:

ALL ROOTES GROUP DEALERS

SUBJECT:

IGNITION TIMING MARKS ON CRANKSHAFT PULLEY

MODELS:

SUPER MINK II - HILLMAN SERIES V & SUNBEAM ALPINE IV

To assist with stroboscopic ignition timing on the subject models, the crankshaft pulley now covers six additional scribe marks at 5° intervals.

The ignition timing on all in line engines, is critical and the settings shown below should be carefully checked during normal service or maintenance.

Ignition Timing-Static (Nominal)

Hillman Super Minx I & 11	90-	110	BTDC
Hillman 1600 Series V	90-	110	n
Husky III	90-	110	11
Sunbeam Alpine IV	90-	110	11
Rapier IV	90-	110	17
" Imp	30		11
Humber Super Snipe	50-	70	? ?

ROOTES MOTORS INCORPORATED

Kenneth Langridge

General Service Manager