

BRAKES

#236

April 28, 1961 No.

TO ALL ROOTES GROUP DEALERS

HUMBER SUPER SNIPE

A certain amount of confusion seems to have arisen regarding the type of brake linings that should be fitted to the above models.

The position has been aggravated due to the supply through normal Parts channels of a limited quantity of front brake friction pads with incorrect linings under Part No. 5038405.

The following details should therefore be studied by all concerned and if any parts drawn for use on these models are found to be incorrect, they should not be used and similarly, if any vehicles are found fitted with incorrect material, the linings should be changed immediately.

	<u>FRONT</u>	<u>REAR</u>
Make of Lining	Mintex	Mintex
Type of Lining	M.33	M.22
Identifications	1- Single dab of green paint	3- evenly spaced dabs of green paint on lining edges.
Humber Part Number	5038405 (Friction Pad Set)	5038415 (Brake shoe with Lining)
Girling Reference No. (Stamped on Carton)	64325088 DX	GB.46038 CQ
Humber Part Number		5038416 (Brake Shoe Lining)
Girling Reference No.		GB.41298 CQ

It is suggested that your Parts stock of the friction pad 5038405 is examined and if it is found to contain any cartons with Girling Part No. 64325088 CV (blue paint marking on pad) then these should be transferred to Part No. 5037614 which is used on the Super Snipe Series II front brakes.

ROOTES MOTORS INCORPORATED

E. J. McGettrick
 E. J. McGettrick, Manager

FJMcG:sg